

Changelog Smart Connect 5.1

02.09.2020

German:

Alte Firmware Revision: MCU 1.044

Neue Firmware Revision: MCU 1.061

Verbesserung der Funktionen:

- Allgemeine Stabilitätsverbesserung
- Neuer Menüpunkt „Subwoofer Setup“
- Neuer SSM Modus „Parallel“ hinzugefügt
- Neuer SSM Modus „Xover“ hinzugefügt
- Einstellbare Übernahmefrequenz für SSM Modus Xover hinzugefügt
- Neuer Filterparameter „Xover kleine Lautsprecher“
- Neues Untermenü „Display Setup“ im Menü Systemeinstellungen
- Neuer Menüpunkt „LED Blinken“ im Display Setup zur Änderung der WiFi-Indikation
- Verbesserung der IR-Lernfunktionen
- Verbesserte Pegelverhältnisse zwischen Stereo und Mehrkanalton
- Anpassungen der Pegelverhältnisse beim Playmode Party

English:

Old Firmware Revision: MCU 1.044

New Firmware Revision: MCU 1.061

Improvement of functions:

- General Stability improvements
- New menu „Subwoofer Setup“
- New SSM mode „Parallel“ added
- New SSM mode „Xover“ added
- Adjustable crossover frequency for SSM mode Xover added
- New filterparameter „Xover small speaker“
- New menu „Display Setup“ in System Setup menu
- New menu item „LED Flashing“ in Display Setup to change the WiFi indication
- Improvements on the IR Learn function
- Improved gain balance between stereo and multichannel audio
- Adjustment on gain settings for playmode Party