

**Changelog Smart Soundbar 9**

29.10.2019

**German:**

Alte Firmware Revision: MCU v1.179; STS 1.12, WIF 10505

Neue Firmware Revision: MCU v1.195; STS 1.17, WIF 12028, DSP 1.78 OSD 1.20

## Verbesserung der Funktionen:

- Allgemeine Stabilitätsverbesserungen
- Update Google Cast auf Version 1.36.145856
- Ab sofort werden STS Verbindungen für zukünftige Updates gespeichert
- Neuer Playmode: MDI = Movie/Music Discrete, sobald Rear Lautsprecher verwendet werden
- Menüpunkt LAN zum ändern der Sprache SYS Menü eingeführt (Deutsch und Englisch)
- Menüpunkt TXP zur Anpassung der Funkleistung im WIS Menü eingefügt
- Menüpunkt CHN zur Anpassung des Funkkanals im WIS Menü eingefügt
- 2,4 GHz Bereich für die Funkverbindung aktiviert
- Menüpunkt EQ (EQ1-3) im SPS Menü zur Raumanpassung

**English:**

Old Firmware Revision: MCU v1.179; STS 1.12, WIF 10505

New Firmware Revision: MCU v1.195; STS 1.17, WIF 12028, DSP 1.78 OSD 1.20

## Improvement of functions:

- General stability improvements
- Updating Google Cast to version 1.36.145856
- From now on, STS connections will be saved for future updates
- New playmode: MDI = Movie/Music Discrete, when rear loudspeaker is used
- Menu item LAN in the SYS menu for changing the language (English and german)
- Menu item TXP in WIS menu for adaption of the wireless performance
- Menu item CHN in WIS menu for adaption of the wireless channel
- 2,4 GHz range for radio connection activated
- Menu item EQ (EQ1-3) for room adjustment in SPS menu